SYRACUSE CITY SCHOOL DISTRICT ED SMITH PK - Grade 8 SCHOOL

SAMPLE DATE: 09/22/2016 ANALYSIS DATES: 11/06/2016 AND 11/08/2016

| ROOM No. & LOCATION | FIXTURE (Sink/Fountain) | ACCESSIBILITY | LABORATORY SAMPLE ID No. | TDK SAMPLE ID No. | RESULTS (ppb) | ACTIONS |
|------------------------------------|----------------------------|---------------------------|-----------------------------|----------------------|---------------|---------------------------------------|
| Rm. 1 - Classroom | Sink | Public Access | EDS-005 | EDS-S103 | 1.9 | None |
| Rm. 1A - Classroom Bathroom | Sink | Public Access | N/A | EDS-S104 | N/A | Fixture out of service; not operating |
| Rm. 2 - Classroom | Sink | Public Access | EDS-007 | EDS-S106 | 2.0 | None |
| Rm. 2A - Classroom Bathroom | Sink | Public Access | EDS-006 | EDS-S105 | 25.0 | SCSD to replace fixture |
| Rm. 4A - Classroom Bathroom | Sink | Public Access | EDS-009 | EDS-S108 | 3.3 | None |
| Rm. 4B - Classroom | Sink | Public Access | EDS-008 | EDS-S107 | 2.9 | None |
| Rm. 5 - Classroom | Sink | Public Access | EDS-010 | EDS-S109 | 2.1 | None |
| Rm. 5A - Classroom Bathroom | Sink | Public Access | EDS-011 | EDS-S110 | 8.9 | None |
| Rm. 6 - Classroom | Sink | Public Access | EDS-012 | EDS-S111 | 2.5 | None |
| Rm. 8C - Classroom Bathroom | Sink | Public Access | EDS-015 | EDS-S114 | 5.9 | None |
| Rm. 8F - Custodian's Bathroom | Sink | Secured - SCSD Staff Only | EDS-016 | EDS-S115 | 1.4 | None |
| Rm. 12 - Classroom | Sink | Public Access | EDS-038 | EDS-S137 | 3.5 | None |
| Rm. 13 - Classroom | Sink | Public Access | EDS-036 | EDS-S135 | 3.9 | None |
| Rm. 14 - Classroom | Sink | Public Access | EDS-037 | EDS-S136 | 5.7 | None |
| Rm. 107 - Classroom | Sink | Public Access | EDS-049 | EDS-S148 | 4.6 | None |
| Rm. 110A - Storage Room | Sink | Secured - SCSD Staff Only | EDS-051 | EDS-S150 | 1.4 | None |
| Rm. 111 - Workroom Bathroom | Sink | Secured - SCSD Staff Only | EDS-050 | EDS-S149 | < 1.0 | None |
| Rm. 112 - Boy's Bathroom | Sink | Public Access | EDS-047 | EDS-S146 | < 1.0 | None |
| Rm. 112 - Boy's Bathroom | Sink | Public Access | EDS-048 | EDS-S147 | < 1.0 | None |
| Rm. 113E - Principal's Bathroom | Sink | Secured - SCSD Staff Only | EDS-002 | EDS-S100 | 3.1 | None |
| Rm. 114 - Nurse's Office | Sink | Public Access | EDS-003 | EDS-S101 | 1.1 | None |
| Rm. 114T - Nurse's Office Bathroom | Sink | Public Access | EDS-004 | EDS-S102 | 3.1 | None |
| Rm. 118 - Girl's Bathroom | Sink | Public Access | EDS-044 | EDS-S143 | 10.0 | None |
| Rm. 118 - Girl's Bathroom | Sink | Public Access | EDS-045 | EDS-S144 | 1.3 | None |
| Rm. 118 - Girl's Bathroom | Sink | Public Access | EDS-046 | EDS-S145 | 2.2 | None |
| Rm. 126B - Hallway/Corridor | Fountain | Public Access | N/A | EDS-F105 | N/A | Fixture out of service |
| Rm. 126B - Hallway/Corridor | Fountain | Public Access | EDS-071 | EDS-F106 | < 1.0 | None |
| Rm. 126D - Hallway/Corridor | Fountain | Public Access | EDS-067 | EDS-F100 | 1.1 | None |
| Rm. 126F - Hallway/Corridor | Fountain | Public Access | EDS-068 | EDS-F101 | < 1.0 | None |

SYRACUSE CITY SCHOOL DISTRICT ED SMITH PK - Grade 8 SCHOOL

SAMPLE DATE: 09/22/2016 ANALYSIS DATES: 11/06/2016 AND 11/08/2016

| ROOM No. & LOCATION | FIXTURE (Sink/Fountain) | ACCESSIBILITY | LABORATORY SAMPLE ID No. | TDK SAMPLE ID No. | RESULTS (ppb) | ACTIONS |
|---------------------------------|----------------------------|---------------------------|-----------------------------|----------------------|---------------|---------------------------------------|
| Rm. 126K - Hallway/Vestibule | Sink | Public Access | EDS-030 | EDS-S129 | 4.6 | None |
| Rm. 126K - Hallway/Vestibule | Sink | Public Access | EDS-031 | EDS-S130 | 11.0 | None |
| Rm. 126K - Hallway/Vestibule | Sink | Public Access | EDS-032 | EDS-S131 | 3.7 | None |
| Rm. 126K - Hallway/Vestibule | Fountain | Public Access | EDS-070 | EDS-F103 | 1.6 | None |
| Rm. 127 - Girl's Bathroom | Sink | Public Access | EDS-013 | EDS-S112 | 2.4 | None |
| Rm. 127 - Girl's Bathroom | Sink | Public Access | EDS-014 | EDS-S113 | 2.7 | None |
| Rm. 129 - Copy Room | Sink | Secured - SCSD Staff Only | EDS-039 | EDS-S138 | 11.0 | None |
| Rm. 135 - Kitchen Bathroom | Sink | Secured - SCSD Staff Only | EDS-023 | EDS-122 | 8.3 | None |
| Rm. 135 - Kitchen | Sink | Secured - SCSD Staff Only | EDS-024 | EDS-S123 | 1.2 | None |
| Rm. 135 - Kitchen | Sink | Secured - SCSD Staff Only | EDS-025 | EDS-S124 | < 1.0 | None |
| Rm. 135 - Kitchen | Sink | Secured - SCSD Staff Only | EDS-026 | EDS-S125 | 2.6 | None |
| Rm. 135 - Kitchen | Sink | Secured - SCSD Staff Only | EDS-027 | EDS-S126 | 3.6 | None |
| Rm. 135 - Kitchen | Sink | Secured - SCSD Staff Only | EDS-028 | EDS-S127 | < 1.0 | None |
| Rm. 135 - Kitchen | Sink | Secured - SCSD Staff Only | EDS-029 | EDS-S128 | 1.9 | None |
| Rm. 140 - Boy's Locker-room | Fountain | Public Access | N/A | EDS-F104 | N/A | Fixture out of service; not operating |
| Rm. 140 - Boy's Locker-room | Sink | Public Access | EDS-034 | EDS-S133 | 48.0 | SCSD to replace fixture |
| Rm. 141A - Boy's Coach Bathroom | Sink | Secured - SCSD Staff Only | EDS-033 | EDS-S132 | 5.3 | None |
| Rm. 154A - Storage Bathroom | Sink | Secured - SCSD Staff Only | EDS-035 | EDS-S134 | 6.6 | None |
| Rm. 156 - Boy's Bathroom | Sink | Public Access | EDS-022 | EDS-121 | 9.2 | None |
| Rm. 156A - Girl's Bathroom | Sink | Public Access | EDS-020 | EDS-S119 | 25.0 | SCSD to replace fixture |
| Rm. 156A - Girl's Bathroom | Sink | Public Access | EDS-021 | EDS-S120 | 16.0 | SCSD to replace fixture |
| Rm. 164 - Library Lounge | Sink | Secured - SCSD Staff Only | EDS-040 | EDS-S139 | 32.0 | SCSD to replace fixture |
| Rm. 169 - Girl's Bathroom | Sink | Public Access | EDS-018 | EDS-S117 | 29.0 | SCSD to replace fixture |
| Rm. 169 - Girl's Bathroom | Sink | Public Access | EDS-019 | EDS-S118 | 27.0 | SCSD to replace fixture |
| Rm. 171 - Boy's Bathroom | Sink | Public Access | EDS-017 | EDS-S116 | 1.1 | None |
| Rm. 176 - Meter/Boiler Room | Sink Adjacent to Meter | Secured - SCSD Staff Only | EDS-001 | EDS-M100 | 5.1 | None |
| Rm. 179 - Cafeteria | Fountain | Public Access | EDS-069 | EDS-F102 | 1.1 | None |
| Rm. B1 - Classroom | Sink | Public Access | EDS-041 | EDS-S140 | 2.4 | None |
| Rm. B5 - Classroom | Sink | Public Access | EDS-042 | EDS-S141 | 6.0 | None |

SYRACUSE CITY SCHOOL DISTRICT ED SMITH PK - Grade 8 SCHOOL

SAMPLE DATE: 09/22/2016 ANALYSIS DATES: 11/06/2016 AND 11/08/2016

| ROOM No. & LOCATION | FIXTURE (Sink/Fountain) | ACCESSIBILITY | LABORATORY SAMPLE ID No. | TDK SAMPLE ID No. | RESULTS (ppb) | ACTIONS |
|---------------------------------------|----------------------------|---------------------------|-----------------------------|----------------------|---------------|---------------------------------------|
| Rm. B5 - Classroom | Sink | Public Access | EDS-043 | EDS-S142 | 1.7 | None |
| Rm. L-2 - Stairwell/Corridor Bathroom | Sink | Secured - SCSD Staff Only | EDS-061 | EDS-S160 | 3.1 | None |
| Rm. 206 - Girl's Bathroom | Sink | Public Access | EDS-057 | EDS-S156 | < 1.0 | None |
| Rm. 206 - Girl's Bathroom | Sink | Public Access | EDS-058 | EDS-S157 | < 1.0 | None |
| Rm. 209 - Classroom | Sink | Public Access | EDS-055 | EDS-S154 | 9.4 | None |
| Rm. 210 - Art Room | Sink | Public Access | EDS-052 | EDS-S151 | 32.0 | SCSD to affix warning sign at fixture |
| Rm. 210 - Art Room | Sink | Public Access | EDS-053 | EDS-S152 | 6.0 | SCSD to affix warning sign at fixture |
| Rm. 210 - Art Room | Sink | Public Access | EDS-054 | EDS-S153 | 21.0 | SCSD to affix warning sign at fixture |
| Rm. 210A - Storage Room | Sink | Secured - SCSD Staff Only | EDS-056 | EDS-S155 | 89.0 | SCSD to affix warning sign at fixture |
| Rm. 216 - Hallway/Corridor | Fountain | Public Access | EDS-072 | EDS-F107 | < 1.0 | None |
| Rm. 216 - Hallway/Corridor | Fountain | Public Access | EDS-073 | EDS-F108 | < 1.0 | None |
| Rm. 217 - Boy's Bathroom | Sink | Public Access | EDS-059 | EDS-S158 | 5.7 | None |
| Rm. 217 - Boy's Bathroom | Sink | Public Access | EDS-060 | EDS-S159 | 1.1 | None |
| Rm. 230A - Hallway/Vestibule | Sink | Public Access | EDS-062 | EDS-S161 | 1.8 | None |
| Rm. 230A - Hallway/Vestibule | Fountain | Public Access | EDS-074 | EDS-F109 | < 1.0 | None |
| Rm. 230A - Hallway/Vestibule | Sink | Public Access | EDS-063 | EDS-S162 | 1.9 | None |
| Rm. 230A - Hallway/Vestibule | Sink | Public Access | EDS-064 | EDS-S163 | 4.1 | None |
| Rm. 231 - Women's Staff Bathroom | Sink | Secured - SCSD Staff Only | EDS-065 | EDS-S164 | 1.2 | None |
| Rm. 232 - Men's Staff Bathroom | Sink | Secured - SCSD Staff Only | EDS-066 | EDS-S165 | 4.3 | None |

Notes

- 1. Water samples collected By: TDK Engineering Associates, P.C. TDK Project No. 2016068-011
- 2. Water samples analyzed By: Life Science Laboratories, Inc. LSL Project ID No. 1616196
- 3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).
- 4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) Subpart 67-4: Lead Testing in School Drinking Water.
- 5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.

