<b>ROOM No. &amp; LOCATION</b>	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS			
BUILDING 'A'									
Rm. B04 - Meter Room	Hose Bib at Meter Assembly	Secured - SCSD Staff Only	047	NM-M200	13.0	None			
Rm. 1-4 - Kitchen/Cafeteria Bathroom	Sink	Secured - SCSD Staff Only	041	NM-S144	4.0	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	028	NM-S131	1.8	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	029	NM-S132	< 1.0	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	030	NM-S133	< 1.0	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	031	NM-S134	2.1	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	032	NM-S135	1.2	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	033	NM-S136	< 1.0	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	034	NM-S137	< 1.0	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	035	NM-S138	1.5	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	036	NM-S139	2.6	None			
Rm. 1-17 - Kitchen Bathroom	Sink	Secured - SCSD Staff Only	037	NM-S140	2.8	None			
Rm. 1-17 - Kitchen Bathroom	Sink	Secured - SCSD Staff Only	038	NM-S141	5.3	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	039	NM-S142	5.2	None			
Rm. 1-17 - Kitchen	Sink	Secured - SCSD Staff Only	040	NM-S143	1.1	None			
Rm. 1-17 - Kitchen	Steamer	Secured - SCSD Staff Only	042	NM-S145	8.9	None			
Rm. 1-17 - Kitchen	Steamer	Secured - SCSD Staff Only	043	NM-S146	< 1.0	None			
Rm. 1-17 - Kitchen	Steamer	Secured - SCSD Staff Only	044	NM-S147	4.6	None			
Rm. 1-17 - Kitchen	Steamer	Secured - SCSD Staff Only	045	NM-S148	3.2	None			
Rm. 1-17 - Kitchen	Ice Machine	Secured - SCSD Staff Only	046	NM-S149	< 1.0	None			
Rm. 1-28 - Custodian's Office	Sink	Secured - SCSD Staff Only	093	NM-S246	2.8	None			
Rm. 1-31 - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	094	NM-S247	100.0	SCSD to post warning sign			
Rm. 1-31 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	095	NM-S248	19.0	SCSD to post warning sign			
Rm. 1-34 - Hallway/Corridor	Fountain	Public Access	142	NM-F207	3.4	None			
Rm. 1-39 - Clinic Office	Sink	Public Access	097	NM-S250	12.0	None			
Rm. 1-40 Clinic Office Bathroom	Sink	Public Access	096	NM-S249	21.0	SCSD to post warning sign			
Rm. 1-41 - Clinic Office Bathroom	Sink	Public Access	098	NM-S251	2.8	None			
Rm. 1-45 - Girl's Locker Room Bathroom	Sink	Public Access	091	NM-S244	43.0	SCSD to post warning sign			



<b>ROOM No. &amp; LOCATION</b>	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS		
BUILDING 'A', Cont.								
Rm. 1-45 - Girl's Locker Room Bathroom	Sink	Public Access	092	NM-S245	32.0	SCSD to post warning sign		
Rm. 1-48 - Boy's Locker Room Office Bathroom	Sink	Secured - SCSD Staff Only	090	NM-S243	5.8	None		
Rm. 1-50 - Boy's Locker Room Bathroom	Sink	Public Access	088	NM-S241	270.0	SCSD to post warning sign		
Rm. 1-50 - Boy's Locker Room Bathroom	Sink	Public Access	089	NM-S242	280.0	SCSD to post warning sign		
Rm. 1-54 - Hallway/Corridor	Fountain	Public Access	140	NM-F205	< 1.0	None		
Rm. 1-54 - Hallway/Corridor	Fountain	Public Access	141	NM-F206	< 1.0	None		
Rm. 1-56 - Girl's Gym Office Bathroom	Sink	Secured - SCSD Staff Only	082	NM-S235	4.7	None		
Rm. 1-61 Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	079	NM-S232	58.0	SCSD to post warning sign		
Rm. 1-61 Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	080	NM-S233	7.1	None		
Rm. 1-62 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	078	NM-S231	11.0	None		
Rm. 1-62 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	076	NM-S229	7.4	None		
Rm. 1-62 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	077	NM-S230	11.0	None		
Rm. 163A - V. Principal's Bathroom	Sink	Secured - SCSD Staff Only	054	NM-S207	4.5	None		
Rm. 1-66 - Instruction Room	Sink	Public Access	081	NM-S234	5.7	None		
Rm. 1-75 - Boy's Locker Room Bathroom	Sink	Public Access	084	NM-S237	< 1.0	None		
Rm. 1-75 - Boy's Locker Room Bathroom	Sink	Public Access	085	NM-S238	< 1.0	None		
Rm. 1-76 - Boy's Gym Office Bathroom	Sink	Secured - SCSD Staff Only	083	NM-S236	8.0	None		
Rm. 1-79 - Hopper Room	Hose Bib at Ice Machine	Public Access	099	NM-S252	1.4	None		
Rm. 1-79 - Hopper Room	Ice Machine	Public Access	100	NM-S253	< 1.0	None		
Rm. 1-87 Boy's Locker Room Office Bathroom	Sink	Secured - SCSD Staff Only	086	NM-S239	32.0	SCSD to post warning sign		
Rm. 1-91 - Boy's Locker Room Bathroom	Sink	Public Access	087	NM-S240	4.6	None		
Rm. 1-92 - Boy's Bathroom	Sink	Public Access	058	NM-S211	1.4	None		
Rm. 1-92 - Boy's Bathroom	Sink	Public Access	059	NM-S212	7.3	None		
Rm. 1-92 - Boy's Bathroom	Sink	Public Access	060	NM-S213	< 1.0	None		
Rm. 1-93 - Girl's Bathroom	Sink	Public Access	055	NM-S208	1.6	None		
Rm. 1-93 - Girl's Bathroom	Sink	Public Access	056	NM-S209	1.0	None		
Rm. 1-93 - Girl's Bathroom	Sink	Public Access	057	NM-S210	2.1	None		
Rm. 2-13 - Library Office	Sink	Secured - SCSD Staff Only	107	NM-S301	1.7	None		



<b>ROOM No. &amp; LOCATION</b>	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS		
BUILDING 'A', Cont.								
Rm. 100 - Home & Careers Room	Sink	Public Access	062	NM-S215	< 1.0	None		
Rm. 100 - Home & Careers Room	Sink	Public Access	063	NM-S216	1.1	None		
Rm. 104C - Classroom Bathroom	Sink	Public Access	064	NM-S217	2.9	None		
Rm. 107 - Boy's Bathroom	Sink	Public Access	065	NM-S218	88.0	SCSD to post warning sign		
Rm. 107 - Boy's Bathroom	Sink	Public Access	066	NM-S219	160.0	SCSD to post warning sign		
Rm. 107 - Boy's Bathroom	Sink	Public Access	067	NM-S220	140.0	SCSD to post warning sign		
Rm. 107 - Boy's Bathroom	Sink	Public Access	068	NM-S221	16.0	SCSD to post warning sign		
Rm. 107 - Boy's Bathroom	Sink	Public Access	069	NM-S222	1.4	None		
Rm. 121 - Hallway/Corridor	Fountain	Public Access	139	NM-F204	< 1.0	None		
Rm. 129 - Girl's Bathroom	Sink	Public Access	070	NM-S223	21.0	SCSD to post warning sign		
Rm. 129 - Girl's Bathroom	Sink	Public Access	071	NM-S224	65.0	SCSD to post warning sign		
Rm. 129 - Girl's Bathroom	Sink	Public Access	072	NM-S225	30.0	SCSD to post warning sign		
Rm. 129 - Girl's Bathroom	Sink	Public Access	073	NM-S226	540.0	SCSD to post warning sign		
Rm. 129 - Girl's Bathroom	Sink	Public Access	074	NM-S227	100.0	SCSD to post warning sign		
Rm. 129 - Girl's Bathroom	Sink	Public Access	075	NM-S228	15.0	SCSD to post warning sign		
Rm. 136H - Guidance Bathroom	Sink	Public Access	061	NM-S214	2.7	None		
Rm. 140 - Nurse's Office	Sink	Public Access	049	NM-S202	2.2	None		
Rm. 140A - Nurse's Office Bathroom	Sink	Public Access	050	NM-S203	3.0	None		
Rm. 141 - Lobby	Fountain	Public Access	138	NM-F203	< 1.0	None		
Rm. 141A - Nurse's Offce	Sink	Public Access	048	NM-S201	< 1.0	None		
Rm. 143 - Hallway/Corridor	Fountain	Public Access	136	NM-F201	1.5	None		
Rm. 151 - Hallway/Corridor	Fountain	Public Access	137	NM-F202	1.6	None		
Rm. 153A - Boy's Bathroom	Sink	Public Access	052	NM-S205	8.1	None		
Rm. 153B - Girl's Bathroom	Sink	Public Access	051	NM-S204	6.9	None		
Rm. 159B - Principal's Bathroom	Sink	Secured - SCSD Staff Only	053	NM-S206	4.8	None		
Rm. 201D - Boy's Bathroom	Sink	Public Access	110	NM-S304	7.9	None		
Rm. 201D - Boy's Bathroom	Sink	Public Access	111	NM-S305	65.0	SCSD to post warning sign		
Rm. 201E - Girl's Bathroom	Sink	Public Access	108	NM-S302	< 1.0	None		



<b>ROOM No. &amp; LOCATION</b>	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS		
BUILDING 'A', Cont.								
Rm. 201E - Girl's Bathroom	Sink	Public Access	109	NM-S303	< 1.0	None		
Rm. 201G - Hallway/Corridor	Fountain	Public Access	144	NM-F306	< 1.0	None		
Rm. 213 - Boy's Bathroom	Sink	Public Access	112	NM-S308	32.0	SCSD to post warning sign		
Rm. 213 - Boy's Bathroom	Sink	Public Access	113	NM-S309	110.0	SCSD to post warning sign		
Rm. 213 - Boy's Bathroom	Sink	Public Access	114	NM-S310	1.1	None		
Rm. 213 - Boy's Bathroom	Sink	Public Access	115	NM-S311	3.0	None		
Rm. 213B - Custodian's Bathroom	Sink	Secured - SCSD Staff Only	116	NM-S312	5.6	None		
Rm. 221 - Hallway/Corridor	Fountain	Public Access	145	NM-F307	< 1.0	None		
Rm. 241 - Girl's Bathroom	Sink	Public Access	117	NM-S313	5.4	None		
Rm. 241 - Girl's Bathroom	Sink	Public Access	118	NM-S314	150.0	SCSD to post warning sign		
Rm. 241 - Girl's Bathroom	Sink	Public Access	119	NM-S315	230.0	SCSD to post warning sign		
Rm. 241 - Girl's Bathroom	Sink	Public Access	120	NM-S316	1.9	None		
Rm. 241 - Girl's Bathroom	Sink	Public Access	121	NM-S317	2.9	None		
Rm. 241 - Girl's Bathroom	Sink	Public Access	122	NM-S318	20.0	SCSD to post warning sign		
Rm. G-2 - Hallway/Vestibule	Fountain	Public Access		NM-F209		Fixture not operating		
Rm. G-4 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	103	NM-S256	13.0	None		
Rm. G-4 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	104	NM-S257	< 1.0	None		
Rm. G-4 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	105	NM-S258	5.4	None		
Rm. G-4 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	106	NM-S259	4.5	None		
Rm. G-5 - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	102	NM-S255	5.6	None		
Rm. G-5 - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	101	NM-S254	2.1	None		
Rm. G-18 - Hallway/Vestibule	Fountain	Public Access	143	NM-F208	1.8	None		
BUILDING 'B'								
Rm. GW-1 - Art Room Bathroom	Sink	Public Access	027	NM-S130	4300.0	SCSD to post warning sign		
Rm. GW-3 - Classroom Bathroom	Sink	Public Access	012	NM-S115	< 1.0	None		
Rm. GW-4 - Classroom	Sink	Public Access	015	NM-S118	2.8	None		
Rm. GW-4 - Classroom	Sink	Public Access	016	NM-S119	3.0	None		
Rm. GW-4 - Classroom	Sink	Public Access	017	NM-S120	< 1.0	None		



<b>ROOM No. &amp; LOCATION</b>	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS		
BUILDING 'B', Cont.								
Rm. GW-4 - Classroom	Sink	Public Access	018	NM-S121	5.5	None		
Rm. GW-4 - Classroom	Sink	Public Access	019	NM-S122	9.0	None		
Rm. GW-4 - Classroom	Sink	Public Access	020	NM-S123	5.6	None		
Rm. GW-4 - Classroom Bathroom	Sink	Public Access	014	NM-S117	< 1.0	None		
Rm. GW-5 - Classroom	Sink	Public Access		NM-S113		Fixture not operating		
Rm. GW-5 - Classroom Bathroom	Sink	Public Access	011	NM-S114	4.5	None		
Rm. GW-6 - Classroom Bathroom	Sink	Public Access	010	NM-S112	7.1	None		
Rm. GW-6 - Classroom	Sink	Public Access		NM-S111		Fixture not operating		
Rm. GW-7 - Classroom Bathroom	Sink	Public Access	008	NM-S109	4.6	None		
Rm. GW-7 - Classroom	Sink	Public Access	009	NM-S110	12.0	None		
Rm. GW-8 - Classroom	Sink	Public Access		NM-S107		Fixture not operating		
Rm. GW-8 - Classroom	Sink	Public Access	007	NM-S108	21.0	SCSD permanently removed fixture from service		
Rm. GW-9 - Classroom Bathroom	Sink	Public Access	005	NM-S105	15.0	SCSD to post warning sign		
Rm. GW-9 - Classroom	Sink	Public Access	006	NM-S106	14.0	None		
Rm. GW-10 - Classroom Bathroom	Sink	Public Access	003	NM-S103	12.0	None		
Rm. GW-10 - Classroom	Sink	Public Access	004	NM-S104	8.3	None		
Rm. GW-11 - Classroom Bathroom	Sink	Public Access	002	NM-S102	5.9	None		
Rm. GW-12 - Classroom Bathroom	Sink	Public Access	001	NM-S100	1.5	None		
Rm. GW-12 - Classroom	Sink	Public Access		NM-S101		Fixture not operating		
Rm. GW-13 - Office	Sink	Secured - SCSD Staff Only	023	NM-S126	5.1	None		
Rm. GW-14 - Office	Sink	Secured - SCSD Staff Only	021	NM-S124	11.0	None		
Rm. GW-17 - Staff Bathroom	Sink	Secured - SCSD Staff Only	013	NM-S116	< 1.0	None		
Rm. GW-18E - Classroom Bathroom	Sink	Public Access	026	NM-S129	8.7	None		
Rm. GW-20 - Men's Bathroom	Sink	Secured - SCSD Staff Only	024	NM-S127	2.1	None		
Rm. GW-20 - Women's Bathroom	Sink	Secured - SCSD Staff Only	025	NM-S128	2.4	None		
Rm. GW-24 - Hallway/Corridor	Fountain	Public Access	134	NM-F100	1.8	None		
Rm. GW-25 - Hallway/Corridor	Fountain	Public Access	135	NM-F101	3.1	None		
Rm. B17 - Boiler/Meter Room	Hose Bib	Secured - SCSD Staff Only	022	NM-S125	35.0	SCSD to post warning sign		



<b>ROOM No. &amp; LOCATION</b>	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS		
BUILDING 'B', Cont.								
Rm. P-102 - Hallway/Corridor	Fountain	Public Access	146	NM-F321	3.1	None		
Rm. P-110 - Staff Locker Room Bathroom	Sink	Secured - SCSD Staff Only	130	NM-S327	7.3	None		
Rm. P-118 - Girl's Bathroom	Sink	Public Access	129	NM-S326	77.0	SCSD to post warning sign		
Rm. P-122 - Girl's Locker Room Bathroom	Sink	Public Access	127	NM-S324	1.6	None		
Rm. P-122 - Girl's Locker Room Bathroom	Sink	Public Access	128	NM-S325	1.5	None		
Rm. P-124 - Boy's Locker Room Bathroom	Sink	Public Access	132	NM-S330	2.9	None		
Rm. P-124 - Boy's Locker Room Bathroom	Sink	Public Access	133	NM-S331	1.6	None		
Rm. P-128 - Boy's Bathroom	Sink	Public Access	131	NM-S329	3.4	None		
Rm. P-130 - Men's Staff Bathroom	Sink	Secured - SCSD Staff Only	125	NM-S322	7.0	None		
Rm. P-132 - Women's Staff Bathroom	Sink	Secured - SCSD Staff Only	126	NM-S323	7.1	None		
Rm. P-137 - Swimming Pool Area	Fountain	Public Access	147	NM-F328	< 1.0	None		
Rm. P-141 - Hopper Room	Sink	Secured - SCSD Staff Only	124	NM-S320	1.4	None		
Rm. P-142 Mechanical/Meter Room	Hose Bib at Meter Assembly	Secured - SCSD Staff Only	123	NM-M319	9.5	None		
		FIELD HOUSE	<b>/CONCESSION STA</b>	ND				
Outside Perimeter	Fountain	Public Access	NMFH-020	NMFH-F100	< 1.0	None		
Outside Perimeter	Fountain	Public Access	NMFH-021	NMFH-F101	< 1.0	None		
Rm. 102 - Coach's Room	Sink	Secured - SCSD Staff Only	NMFH-001	NMFH-S100	< 1.0	None		
Rm. T2 - Home Team Bathroom	Sink	Public Access	NMFH-002	NMFH-S101	2.2	None		
Rm. T2 - Home Team Bathroom	Sink	Public Access	NMFH-003	NMFH-S102	1.1	None		
Rm. T1 - Visiting Team Bathroom	Sink	Public Access	NMFH-004	NMFH-S103	2.4	None		
Rm. T1 - Visiting Team Bathroom	Sink	Public Access	NMFH-005	NMFH-S104	< 1.0	None		
Outside Perimeter	Hose Bib	Public Access	NMFH-006	NMFH-S105	< 1.0	None		
Rm. T5 - Official's Bathroom	Sink	Secured - SCSD Staff Only	NMFH-007	NMFH-S106	2.0	None		
Concessions Stand	Sink	Secured - SCSD Staff Only	NMFH-008	NMFH-S107	4.4	None		
Concessions Stand	Sink	Secured - SCSD Staff Only	NMFH-009	NMFH-S108	3.6	None		
Concessions Stand	Sink	Secured - SCSD Staff Only	NMFH-010	NMFH-S109	2.5	None		
Rm. T4 - Men's Bathroom	Sink	Public Access	NMFH-011	NMFH-S110	< 1.0	None		
Rm. T4 - Men's Bathroom	Sink	Public Access	NMFH-012	NMFH-S111	< 1.0	None		



#### SYRACUSE CITY SCHOOL DISTRICT NOTTINGHAM HIGH SCHOOL

SAMPLE DATE: 10/10/2016 ANALYSIS DATES: 12/13, 14, 16, 27, 29/2016 and 01/04/2017

<b>ROOM No. &amp; LOCATION</b>	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LABORATORY SAMPLE ID No.	TDK SAMPLE ID No.	RESULTS (ppb)	ACTIONS
		FIELD HOUSE/C	ONCESSION STANE	, Cont.		
Rm. T4 - Men's Bathroom	Sink	Public Access	NMFH-013	NMFH-S112	1.8	None
Rm. T4 - Men's Bathroom	Sink	Public Access		NMFH-S113		Fixture out of operation
Rm. T3 - Women's Bathroom	Sink	Public Access	NMFH-014	NMFH-S114	1.1	None
Rm. T3 - Women's Bathroom	Sink	Public Access	NMFH-015	NMFH-S115	< 1.0	None
Rm. T3 - Women's Bathroom	Sink	Public Access	NMFH-016	NMFH-S116	1.1	None
Rm. T3 - Women's Bathroom	Sink	Public Access	NMFH-017	NMFH-S117	< 1.0	None
Rm. T3 - Women's Bathroom	Sink	Public Access	NMFH-018	NMFH-S118	< 1.0	None
Rm. T3 - Women's Bathroom	Sink	Public Access	NMFH-019	NMFH-S119	2.2	None

Notes:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-030 and 044

2. Water samples analyzed By: Life Science Laboratories, Inc. - LSL Project ID Nos. 1621049 and 1620404

3. New York State Department of Health Standard for Lead in Drinking Water is 15 parts per billion (ppb).

4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.

5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.

