SYRACUSE CITY SCHOOL DISTRICT DELAWARE ELEMENTARY SCHOOL

| ROOM No. & LOCATION | FIXTURE (Sink/Fountain) | ACCESSIBILITY | LAB SAMPLE I.D. No. | TDK SAMPLE I.D. No. | 06/22/23 RESULTS (ppb) | 06/22/23 ORIGINAL ACTIONS | LAB RE-SAMPLE I.D. No. | 01/09/24 RE-SAMPLE RESULTS (ppb) | 01/09/24 RE-SAMPLE ACTIONS |
|-------------------------------|----------------------------|---------------------------|---------------------------|---------------------------|------------------------------|---------------------------------|------------------------------|---|----------------------------------|
| Rm. 101 - Classroom | Sink | Public Access | 042 | DE-S332 | <1.0 | None | | | |
| Rm. 101 - Classroom | Fountain | Public Access | 043 | DE-F310 | 2.9 | None | | | |
| Rm. 102 - Classroom | Sink | Public Access | 040 | DE-S330 | 137 | See Note 7. | 017 | <1.0 | None |
| Rm. 102 - Classroom | Fountain | Public Access | 041 | DE-F309 | 9.7 | See Note 6. | 016 | 1.3 | None |
| Rm. 103 - Classroom | Sink | Public Access | 038 | DE-S325 | 226 | See Note 7. | 015 | <1.0 | None |
| Rm. 103 - Classroom | Fountain | Public Access | 039 | DE-F307 | 10.5 | See Note 6. | 014 | <1.0 | None |
| Rm. 104 - Classroom | Fountain | Public Access | 025 | DE-F306 | 216 | See Note 6. | 012 | <1.0 | None |
| Rm. 104A - Classroom Bathroom | Sink | Public Access | 024 | DE-S323 | 2.3 | None | | | |
| Rm. 105 - Classroom | Fountain | Public Access | 027 | DE-F308 | 127 | See Note 6. | 013 | <1.0 | None |
| Rm. 105A - Classroom Bathroom | Sink | Public Access | 026 | DE-S327 | <1.0 | None | | | |
| Rm. 108 - Classroom | Sink | Public Access | 023 | DE-S320 | 26.2 | See Note 7. | 011 | <1.0 | None |
| Rm. 108 - Classroom | Fountain | Public Access | 022 | DE-F304 | 127 | See Note 6. | 010 | <1.0 | None |
| Rm. 110 - Classroom | Sink | Public Access | 019 | DE-S318 | 34.3 | See Note 7. | 009 | <1.0 | None |
| Rm. 110 - Classroom | Fountain | Public Access | 020 | DE-F303 | 17.7 | See Note 6. | 008 | 4.1 | None |
| Rm. 112 - Classroom | Sink | Public Access | 017 | DE-S316 | 26.9 | See Note 7. | 018 | 45.1 | See Note 7. |
| Rm. 112 - Classroom | Fountain | Public Access | 016 | DE-F302 | 5.3 | See Note 6. | | | See Note 6. |
| Rm. 118 - Teacher's Lounge | Sink | Secured - SCSD Staff Only | 015 | DE-S306 | <1.0 | None | | | |
| Rm. 120 - Serving Room | Sink | Secured - SCSD Staff Only | 034 | DE-S301 | 5.2 | See Note 7. | 004 | <1.0 | None |
| Rm. 120 - Serving Room | Sink | Secured - SCSD Staff Only | 035 | DE-S302 | 4.6 | None | | | |
| Rm. 120 - Serving Room | Sink | Secured - SCSD Staff Only | 036 | DE-S303 | 1.6 | None | | | |
| Rm. 120 - Serving Room | Sink | Secured - SCSD Staff Only | 037 | DE-S304 | 128 | See Note 6. | 001 | <1.0 | None |
| Rm. 120A - Kitchen Bathroom | Sink | Secured - SCSD Staff Only | 011 | DE-S305 | 3.7 | None | 002 | 1.5 | None |
| Rm. 123A - Hallway/Corridor | Fountain | Public Access | 013 | DE-F301 | <1.0 | None | | | |
| Rm. 123A - Hallway/Corridor | Fountain | Public Access | 014 | DE-F301A | <1.0 | None | | | |
| Rm. 129 - Hallway/Corridor | Fountain | Public Access | 021 | DE-F305 | 6.1 | See Note 6. | 007 | 1.2 | None |
| Rm. 190A - Classroom Bathroom | Sink | Public Access | 018 | DE-S317 | <1.0 | None | | | |
| Rm. 209 - Nurse's Room | Sink | Public Access | 054 | DE-S345 | 254 | See Note 7. | 033 | <1.0 | None |

SYRACUSE CITY SCHOOL DISTRICT DELAWARE ELEMENTARY SCHOOL

| ROOM No. & LOCATION | FIXTURE (Sink/Fountain) | ACCESSIBILITY | LAB SAMPLE I.D. No. | TDK SAMPLE I.D. No. | 06/22/23 RESULTS (ppb) | 06/22/23 ACTIONS | LAB SAMPLE I.D. No. | 01/09/2024 RE-SAMPLE RESULTS (ppb) | 01/09/2024 RE-SAMPLE ACTIONS |
|-----------------------------------|----------------------------|---------------------------|---------------------------|---------------------------|------------------------------|---------------------|---------------------------|---|------------------------------------|
| Rm. 232 - Hallway/Corridor | Fountain | Public Access | 033 | DE-F311 | <1.0 | None | | | |
| Rm. 235 - Hallway/Vestibule | Sink | Public Access | 030 | DE-S334 | 739 | See Note 7. | 042 | <1.0 | None |
| Rm. 235 - Hallway/Vestibule | Sink | Public Access | 031 | DE-S335 | 583 | See Note 7. | 043 | <1.0 | None |
| Rm. 235 - Hallway/Vestibule | Sink | Public Access | 032 | DE-S336 | 215 | See Note 7. | 044 | <1.0 | None |
| Rm. 240 - Hallway/Vestibule | Sink | Public Access | 050 | DE-S346 | 2100 | See Note 7. | 030 | <1.0 | None |
| Rm. 240 - Hallway/Vestibule | Sink | Public Access | 051 | DE-S347 | <1.0 | None | | | |
| Rm. 240 - Hallway/Vestibule | Sink | Public Access | 052 | DE-S348 | 921 | See Note 7. | 031 | <1.0 | None |
| Rm. 240 - Hallway/Vestibule | Sink | Public Access | 053 | DE-S349 | 211 | See Note 7. | 032 | <1.0 | None |
| Rm. 240 - Hallway/Vestibule | Fountain | Public Access | 044 | DE-F312 | <1.0 | None | | | |
| Rm. 245 - Gym Lobby | Fountain | Public Access | 049 | DE-F313 | <1.0 | None | | | |
| Rm. 306A - Classroom Bathroom | Sink | Public Access | 009 | DE-S359 | 405 | See Note 7. | 026 | <1.0 | None |
| Rm. 308A - Classroom Bathroom | Sink | Public Access | 008 | DE-S358 | <1.0 | None | | | None |
| Rm. 319 - Work Room | Sink | Public Access | 002 | DE-S352 | 689 | See Note 7. | 020 | <1.0 | None |
| Rm. 324A - Hallway/Corridor | Fountain | Public Access | 001 | DE-F314 | 107 | See Note 6. | 019 | <1.0 | None |
| Rm. 330A - Hallway/Vestibule | Fountain | Public Access | 010 | DE-F317 | 1.3 | None | | | |
| Rm. 335 - Hallway/Vestibule | Sink | Public Access | 045 | DE-S360 | 423 | See Note 7. | 027 | <1.0 | None |
| Rm. 335 - Hallway/Vestibule | Sink | Public Access | 046 | DE-S361 | 200 | See Note 7. | 028 | <1.0 | None |
| Rm. 335 - Hallway/Vestibule | Sink | Public Access | 047 | DE-S362 | 257 | See Note 7. | 029 | <1.0 | None |
| Rm. 340 - Hallway/Vestibule | Sink | Public Access | 003 | DE-S354 | 1360 | See Note 7. | 021 | <1.0 | None |
| Rm. 340 - Hallway/Vestibule | Sink | Public Access | 004 | DE-S355 | 330 | See Note 7. | 022 | <1.0 | None |
| Rm. 340 - Hallway/Vestibule | Sink | Public Access | 006 | DE-S356 | 1330 | See Note 7. | 023 | <1.0 | None |
| Rm. 340 - Hallway/Vestibule | Sink | Public Access | 007 | DE-S357 | 250 | See Note 7. | 024 | <1.0 | None |
| Rm. 340 - Hallway/Vestibule | Fountain | Public Access | 005 | DE-F315 | 9.5 | See Note 6. | 025 | <1.0 | None |
| Rm. 429 - Hallway/Corridor | Fountain | Public Access | 048 | DE-F316 | 3.5 | None | | | |
| Rm. 120 - Serving Room | Convotherm Oven | Secured - SCSD Staff Only | 012 | DE-C1000A | <1.0 | None | | | |
| Rm. 206B - Clinical Lab | Sink (Spray Hose) | Public Access | 029 | DE-S1002 | 598 | See Note 7. | 035 | 1.8 | None |
| Rm. 209 - Nurse's Room - Bathroom | Sink | Public Access | 028 | DE-S344 | <1.0 | None | | | |

SYRACUSE CITY SCHOOL DISTRICT DELAWARE ELEMENTARY SCHOOL

| ROOM No. & LOCATION | FIXTURE (Sink/Fountain) | ACCESSIBILITY | LAB SAMPLE I.D. No. | TDK SAMPLE I.D. No. | 06/22/23 RESULTS (ppb) | 06/22/23 ORIGINAL ACTIONS | LAB SAMPLE I.D. No. | 01/09/24 RE-SAMPLE RESULTS (ppb) | 01/09/24 RE-SAMPLE ACTIONS |
|-------------------------------|----------------------------|---------------------------|---------------------------|---------------------------|------------------------------|---------------------------------|---------------------------|---|----------------------------------|
| Rm. 209 - Nurse's Room | Sink | Public Access | 054 | DE-S345 | 254 | See Note 7. | 033 | <1.0 | None |
| Rm. 209 - Nurse's Room | Sink | Public Access | | DE-S345A | | None | 034 | 2.6 | None |
| Rm. 120A - Kitchen Bathroom | Sink | Secured - SCSD Staff Only | | DE-S305 | | None | 002 | 1.5 | None |
| Rm. 206B - Clinical Lab | Sink | Public Access | | DE-S341 | | None | 036 | 1.1 | None |
| Rm. 206A - Clinic Bathroom | Sink | Public Access | | DE-S342 | | None | 037 | <1.0 | None |
| Rm. 206D - Dental Room | Sink | Public Access | | DE-S339 | | None | 038 | <1.0 | None |
| Rm. 206C - Treatment Center | Sink | Public Access | | DE-S340 | | None | 039 | <1.0 | None |
| Rm. 206F - Nurse's Room | Sink | Public Access | | DE-S337 | | None | 040 | 7.5 | See Note 7. |
| Rm. 206E - Sick/Rest Room | Sink | Public Access | | DE-S338 | | None | 041 | <1.0 | None |
| Rm. 112A - Classroom Bathroom | Sink | Public Access | | DE-S315 | | None | 006 | <1.0 | None |

Notes [June 22, 2023 Event]:

- 1. Water samples collected by: TDK Engineering Associates, P.C. TDK Project No. 2016068-022.
- 2. Water samples analyzed by: Pace Analytical Services, LLC Pace Project No. 70260836.
- 3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
- 4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) Subpart 67-4: Lead Testing in School Drinking Water.
- 5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
- 6. Fixture repaired by SCSD.
- 7. Fixture removed and replaced by SCSD.

Notes [January 09, 2024 Event]:

- 1. Water samples collected by: TDK Engineering Associates, P.C. TDK Project No. 2016068-022.
- 2. Water samples analyzed by: Pace Analytical Services, LLC Pace Project No. 70283643.
- 3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
- 4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) Subpart 67-4: Lead Testing in School Drinking Water.
- 5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
- 6. Fixture inoperative. Replaced by SCSD. Resample pending.
- 7. Fixture replaced by SCSD. Resample pending.

