

SYRACUSE CITY SCHOOL DISTRICT
BELLEVUE ELEMENTARY SCHOOL
SAMPLE DATE: 12/12/23 ANALYSIS DATE: 12/15/23

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	12/12/23 RESULTS (ppb)	12/12/23 ACTIONS
Rm. 210 - Cafetorium	Fountain	Public Access	027	BE-F111	<1.0	None
Rm. 210 - Cafetorium	Fountain	Public Access	028	BE-F111A	<1.0	None
Rm. 208 - Kitchen	Sink	Secured - SCSD Staff Only	024	BE-S138	2.2	None
Rm. 208 - Kitchen	Sink	Secured - SCSD Staff Only	022	BE-S139	<1.0	None
Rm. C200 - Hallway/Corridor	Fountain	Public Access	035	BE-F114	1.7	None
Rm. 201 - Nurse's Office	Sink	Public Access	036	BE-S148	<1.0	None
Rm. 100 - Pre-K Classroom	Sink	Public Access	001	BE-S1000	1.0	None
Rm. 100 - Pre-K Classroom	Fountain	Public Access	002	BE-F1000	3.9	None
Rm. 101 - Pre-K Classroom	Sink	Public Access	003	BE-S1002	<1.0	None
Rm. 101 - Pre-K Classroom	Fountain	Public Access	--	BE-F1001	--	See Note 6.
Rm. 102 - Pre-K Classroom	Sink	Public Access	004	BE-S1004	<1.0	None
Rm. 102 - Pre-K Classroom	Fountain	Public Access	005	BE-F1002	4.2	None
Rm. 111 - Kindergarten Classroom	Sink	Public Access	008	BE-S1006	<1.0	None
Rm. 111 - Kindergarten Classroom	Fountain	Public Access	--	BE-F1003	--	See Note 6.
Rm. 112 - Kindergarten Classroom	Sink	Public Access	009	BE-S1008	<1.0	None
Rm. 112 - Kindergarten Classroom	Fountain	Public Access	--	BE-F1004	--	See Note 6.
Rm. 116 - Kindergarten Classroom	Sink	Public Access	014	BE-S1010	<1.0	None
Rm. 116 - Kindergarten Classroom	Fountain	Public Access	013	BE-F1005	<1.0	None
Rm. 117 - Kindergarten Classroom	Fountain	Public Access	--	BE-F1006	--	See Note 6.
Rm. 117 - Kindergarten Classroom	Sink	Public Access	015	BE-S1012	<1.0	None
Rm. C104 - Hallway/Corridor	Sink	Public Access	020	BE-S1017	<1.0	None
Rm. C104 - Hallway/Corridor	Sink	Public Access	019	BE-S1018	<1.0	None
Rm. C104 - Hallway/Corridor	Sink	Public Access	018	BE-S1019	<1.0	None
Rm. C105 - Hallway/Corridor	Fountain	Public Access	016	BE-F1007	<1.0	None
Rm. C105 - Hallway/Corridor	Fountain	Public Access	017	BE-F1008	<1.0	None
Rm. 205 - Teacher's Lounge	Sink	Secured - SCSD Staff Only	021	BE-S1020	<1.0	None
Rm. 208 - Kitchen	Sink (Faucet)	Secured - SCSD Staff Only	025	BE-S1025	1.2	None

**SYRACUSE CITY SCHOOL DISTRICT
BELLEVUE ELEMENTARY SCHOOL**
SAMPLE DATE: 12/12/23 ANALYSIS DATE: 12/15/23

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	12/12/23 RESULTS (ppb)	12/12/23 ACTIONS
Rm. 208 - Kitchen	Sink (Spray)	Secured - SCSD Staff Only	026	BE-S1026	<1.0	None
Rm. C204 - Hallway/Corridor	Sink	Public Access	030	BE-S1029	<1.0	None
Rm. C204 - Hallway/Corridor	Sink	Public Access	031	BE-S1030	<1.0	None
Rm. C204 - Hallway/Corridor	Sink	Public Access	032	BE-S1031	<1.0	None
Rm. C205 - Hallway/Corridor	Fountain	Public Access	033	BE-F1009	<1.0	None
Rm. C205 - Hallway/Corridor	Fountain	Public Access	034	BE-F1010	<1.0	None
Rm. 115 - Music Classroom	Sink	Public Access	010	BE-S1037	9.7	See Note 7.
Rm. 115 - Music Classroom	Sink	Public Access	011	BE-S1038	2.4	None
Rm. 115 - Music Classroom	Sink	Public Access	012	BE-S1039	7.4	See Note 7.
Rm. C103 - Hallway/Corridor	Fountain	Public Access	007	BE-F3000	<1.0	None
Rm. C103 - Hallway/Corridor	Fountain	Public Access	006	BE-F3001	<1.0	None
Rm. C103 - Hallway/Corridor	Fountain	Public Access	023	BE-C1000	<1.0	None
Rm. 211 - Parent Room	Sink	Public Access	029	BE-S2000	2.8	None

Notes [December 12, 2023 Event]:

1. Water samples collected By: TDK Engineering Associates, P.C. - TDK Project No. 2016068-009.
2. Water samples analyzed By: Pace Analytical Services, LLC - Pace Project No. 70280712.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation of Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture inoperative. SCSD to evaluate for repair or removal.
7. Fixture repaired by SCSD. Resampling pending.