

**SYRACUSE CITY SCHOOL DISTRICT
ELMWOOD ELEMENTARY SCHOOL**
SAMPLE DATE: 08/10/23 ANALYSIS DATE: 08/14/23

ROOM No. & LOCATION	FIXTURE (Sink / Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	08/10/23 RESULTS (ppb)	08/10/23 ACTIONS
Rm. 04 - Kitchen	Sink	Secured - SCSD Staff Only	029	ED-S202	3.4	None
Rm. 04 - Kitchen	Sink	Secured - SCSD Staff Only	030	ED-S203	3.1	None
Rm. 04 - Kitchen	Sink	Secured - SCSD Staff Only	028	ED-S204	9.0	See Note 9.
Rm. 40 - Hallway/Vestibule	Fountain	Public Access	003	ED-F201	<1.0	None
Rm. 40 - Hallway/Vestibule	Sink	Public Access	002	ED-S206	1.4	None
Rm. 40 - Hallway/Vestibule	Sink	Public Access	001	ED-S207	1.6	None
Rm. 59 - Classroom	Sink	Public Access	006	ED-S100	<1.0	None
Rm. 59 - Classroom	Sink	Public Access	007	ED-S101	12.2	See Note 8.
Rm. 61 - Classroom	Sink	Public Access	005	ED-S102	4.6	None
Rm. 63 - Classroom	Sink	Public Access	004	ED-S107	<1.0	None
Rm. 68 - Storage Room	Sink	Secured - SCSD Staff Only	008	ED-S105	35.4	See Note 8.
Rm. 105 - Resource Room	Sink	Public Access	010	ED-S125	<1.0	None
Rm. 106 - Teacher's Lounge	Sink	Secured - SCSD Staff Only	009	ED-S122	<1.0	None
Rm. 124 - Hallway/Vestibule	Fountain	Public Access	---	ED-F101	---	See Note 6.
Rm. 124 - Hallway/Vestibule	Sink	Public Access	036	ED-S115	1.0	None
Rm. 124 - Hallway/Vestibule	Sink	Public Access	035	ED-S116	<1.0	None
Rm. 124 - Hallway/Vestibule	Sink	Public Access	034	ED-S117	<1.0	None
Rm. 135 - Classroom Bathroom	Sink	Public Access	---	ED-S213	---	See Note 7.
Rm. 136 - Classroom	Sink	Public Access	022	ED-S214	3.6	None
Rm. 137 - Classroom	Sink	Public Access	023	ED-S215	<1.0	None
Rm. 138 - Classroom	Sink	Public Access	---	ED-S217	---	See Note 6.
Rm. 139 - Hallway/Corridor	Fountain	Public Access	033	ED-F102	<1.0	None
Rm. 139 - Hallway/Corridor	Fountain	Public Access	031	ED-F103	<1.0	None
Rm. 139 - Hallway/Corridor	Fountain (Sensor)	Public Access	032	ED-F103A	<1.0	None
Rm. 142A - Classroom	Fountain	Public Access	027	ED-F100	1.4	None
Rm. 142B - Resource Room	Sink	Public Access	037	ED-S110	<1.0	None
Rm. 146 - Classroom	Sink	Public Access	025	ED-S111	<1.0	None
Rm. 146 - Classroom	Sink	Public Access	026	ED-S112	1.6	None
Rm. 208 - Classroom	Sink	Public Access	017	ED-S232	4.5	None

**SYRACUSE CITY SCHOOL DISTRICT
ELMWOOD ELEMENTARY SCHOOL**
SAMPLE DATE: 08/10/23 ANALYSIS DATE: 08/14/23

ROOM No. & LOCATION	FIXTURE (Sink / Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	08/10/23 RESULTS (ppb)	08/10/23 ACTIONS
Rm. 212 - Work Room	Sink	Secured - SCSD Staff Only	018	ED-S237	<1.0	None
Rm. 215 - Hallway/Vestibule	Sink	Public Access	019	ED-S233	<1.0	None
Rm. 215 - Hallway/Vestibule	Sink	Public Access	020	ED-S235	<1.0	None
Rm. 215 - Hallway/Vestibule	Sink	Public Access	021	ED-S236	1.2	None
Rm. 215 - Hallway/Vestibule	Fountain	Public Access	---	ED-F203	---	See Note 6.
Rm. 224 - Classroom	Sink	Public Access	---	ED-S223	---	See Note 6.
Rm. 228 - Classroom	Sink	Public Access	038	ED-S121	<1.0	None
Rm. 229 - Classroom	Sink	Public Access	011	ED-S222	1.0	None
Rm. 230 - Hallway/Vestibule	Fountain	Public Access	012	ED-F202	<1.0	None
Rm. 230 - Hallway/Vestibule	Sink	Public Access	013	ED-S224	1.1	None
Rm. 230 - Hallway/Vestibule	Sink	Public Access	014	ED-S225	1.6	None
Rm. 230 - Hallway/Vestibule	Sink	Public Access	015	ED-S226	<1.0	None
Rm. 230 - Hallway/Vestibule	Sink	Public Access	016	ED-S227	<1.0	None
Rm. 04 - Kitchen	Convotherm Oven Sprayer	Secured - SCSD Staff Only	---	ED-C1000	---	See Note 6.

Notes [August 10, 2023 Event]:

1. Water samples collected by: TDK Engineering Associates, P.C. - TDK Project No. 2016068-039.
2. Water samples analyzed by: Pace Analytical Services, LLC - Pace Project ID No. 70266565.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture inoperative. SCSD to evaluate for repair or removal.
7. Fixture inaccessible.
8. Fixture removed and replace by SCSD. Resampling pending.
9. Fixture repaired by SCSD. Resampling pending.