

**SYRACUSE CITY SCHOOL DISTRICT**  
**WEBSTER ELEMENTARY SCHOOL**  
SAMPLE DATE: 06/13/2023    ANALYSIS DATE: 06/16/2023

ROOM No. & LOCATION	FIXTURE (Sink / Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	06/13/23 RESULTS (ppb)	06/13/23 ACTIONS
Rm. 012A - Classroom (012) Bathroom	Sink	Public Access	027	WR-S137	<1.0	None
Rm. 021 - Hallway/Corridor	Fountain	Public Access	026	WR-F107	<1.0	None
Rm. 100D - Hallway/Corridor	Fountain	Public Access	001	WR-F101	2.1	None
Rm. 100D - Hallway/Corridor	Fountain	Public Access	002	WR-F102	<1.0	None
Rm. 100Q - Hallway/Corridor	Fountain	Public Access	009	WR-F100	1.3	None
Rm. 100T - Hallway/Corridor	Fountain	Public Access	013	WR-F104	<1.0	None
Rm. 100T - Hallway/Corridor	Fountain (Sensor)	Public Access	014	WR-F104A	<1.0	None
Rm. 110 - Hallway/Vestibule	Sink	Public Access	021	WR-S128	1.8	None
Rm. 110 - Hallway/Vestibule	Sink	Public Access	020	WR-S129	1.3	None
Rm. 110 - Hallway/Vestibule	Sink	Public Access	019	WR-S130	2.1	None
Rm. 110 - Hallway/Vestibule	Fountain	Public Access	018	WR-F105	2.4	None
Rm. 114 - Hallway/Vestibule	Sink	Public Access	031	WR-S138	2.1	None
Rm. 114 - Hallway/Vestibule	Sink	Public Access	030	WR-S139	3.8	None
Rm. 114 - Hallway/Vestibule	Sink	Public Access	029	WR-S140	3.5	None
Rm. 114 - Hallway/Vestibule	Fountain	Public Access	028	WR-F108	2.1	None
Rm 114AA- Nurse's Office Exam Room	Sink	Public Access	---	WR-S121	---	See Note 6.
Rm. 114B - Nurse's Office Bathroom	Sink	Public Access	016	WR-S120	2.5	None
Rm. 118A - Library Office	Sink	Secured - SCSD Staff Only	015	WR-S119	3.6	None
Rm. 137 - Classroom Bathroom	Sink	Public Access	003	WR-S105	2.3	None
Rm. 144 - Classroom	Fountain	Public Access	010	WR-F103	3.3	None
Rm. 144B - Classroom (144) Bathroom	Sink	Public Access	011	WR-S116	1.7	None
Rm. 145 - Classroom	Sink	Public Access	012	WR-S115	3.6	None
Rm. 152A - Kitchen	Sink	Secured - SCSD Staff Only	004	WR-S100	6.7	See Note 7.
Rm. 152A - Kitchen	Sink	Secured - SCSD Staff Only	005	WR-S101	<1.0	None
Rm. 152A - Kitchen	Sink Hose	Secured - SCSD Staff Only	006	WR-S101A	<1.0	None
Rm. 152A - Kitchen	Sink	Secured - SCSD Staff Only	007	WR-S102	2.5	None
Rm. 152A - Kitchen	Cooker Spray	Secured - SCSD Staff Only	008	WR-C100	53.6	See Note 8.

**SYRACUSE CITY SCHOOL DISTRICT  
WEBSTER ELEMENTARY SCHOOL**  
SAMPLE DATE: 06/13/2023    ANALYSIS DATE: 06/16/2023

ROOM No. & LOCATION	FIXTURE (Sink / Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	06/13/23 RESULTS (ppb)	06/13/23 ACTIONS
Rm. 178 - Teacher's Lounge	Sink	Secured - SCSD Staff Only	017	WR-S124	2.9	None
Rm. 211 - Hallway/Vestibule	Sink	Public Access	025	WR-S133	2.6	None
Rm. 211 - Hallway/Vestibule	Sink	Public Access	024	WR-S134	1.2	None
Rm. 211 - Hallway/Vestibule	Sink	Public Access	023	WR-S135	1.1	None
Rm. 211 - Hallway/Vestibule	Fountain	Public Access	022	WR-F106	1.4	None

Notes [June 13, 2023 Event]:

1. Water samples collected by: TDK Engineering Associates, P.C. - TDK Project No. 2016068-003.
2. Water samples analyzed by: Pace Analytical Services, LLC - Pace Project No. 70259562.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture inoperative. SCSD to evaluate for repair or removal.
7. Fixture removed and replaced by SCSD. Resampling pending.
8. Filter repaired by SCSD. Resampling pending.