SYRACUSE CITY SCHOOL DISTRICT FRANKLIN ELEMENTARY SCHOOL

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	07/21/23 RESULTS (ppb)	07/21/23 ORIGINAL ACTIONS	LAB RE-SAMPLE I.D. No.	04/03/24 RE-SAMPLE RESULTS (ppb)	04/03/24 RE-SAMPLE ACTIONS
Rm. A100 - Hallway/Vestibule	Fountain	Public Access	012	FN-F207	<1.0	None			
Rm. A100 - Hallway/Vestibule	Fountain	Public Access	013	FN-F207A	<1.0	None	-1		
Rm. 201 - Nurse Office	Fountain	Public Access	014	FN-S208	<1.0	None	1		
Rm. 100 - Classroom	Sink	Public Access	037	FN-S203	2.5	None	-1		
Rm. 100 - Classroom	Fountain	Public Access	036	FN-F204	<1.0	None	-1		
Rm. 102 - Classroom	Fountain	Public Access	038	FN-F205	14.7	See Note 6.	003	2.2	None
Rm. 103 - Classroom	Sink	Public Access	046	FN-S205	2.2	None	1		
Rm. 103 - Classroom	Fountain	Public Access	045	FN-F206	2.4	None			
Rm. 104 - Classroom	Sink	Public Access	048	FN-S110	1.4	None			
Rm. 104 - Classroom	Fountain	Public Access	047	FN-F107	5.7	See Note 6.	004	<1.0	None
Rm. 106 - Classroom	Sink	Public Access	050	FN-S109	1.6	None			
Rm. 106 - Classroom	Fountain	Public Access	049	FN-F106	4.8	None			
Rm. 112 - Classroom	Sink	Public Access	051	FN-S107	1.4	None			
Rm. 112 - Classroom	Fountain	Public Access	052	FN-F105	132	See Note 6.	005	<1.0	None
Rm. 113 - Classroom	Fountain	Public Access	053	FN-F104	3.7	None			
Rm. 114 - Classroom	Sink	Public Access	055	FN-S105	2	None			
Rm. 114 - Classroom	Fountain	Public Access	056	FN-F103	6.7	See Note 6.	006	<1.0	None
Rm. 116 - Classroom	Fountain	Public Access	057	FN-F102	4.5	None			
Rm. 117 - Classroom	Fountain	Public Access	059	FN-F101	3.7	None			
Rm. 119 - Hallway/Vestibule	Sink	Public Access	058	FN-S100	<1.0	None			
Rm. 119 - Hallway/Vestibule	Sink	Public Access	060	FN-S101	<1.0	None			
Rm. 119 - Hallway/Vestibule	Sink	Public Access	061	FN-S102	<1.0	None			
Rm. 119 - Hallway/Vestibule	Fountain	Public Access	054	FN-F100	1.2	None			
Rm. 201 - Nurse Office	Sink	Public Access	015	FN-S209	5.8	See Note 6.	002	<1.0	None
Rm. 123 - Classroom	Fountain	Public Access	062	FN-F200	<1.0	None			
Rm. 202 - Health Center	Sink	Public Access	019	FN-S212A	8.8	See Note 8.			
Rm. 124 - Classroom	Fountain	Public Access	063	FN-F201	<1.0	None			
Rm. 208 - Teacher's Lounge	Sink	Public Access	022	FN-S130	2.4	None			
Rm. 125 - Classroom	Fountain	Public Access	034	FN-F203	<1.0	None			
Rm. 131 - Kitchen	Sink	Secured - SCSD Staff Only	044	FN-S112	1.5	None			
Rm. 131 - Kitchen	Sink	Secured - SCSD Staff Only	040	FN-S113	2.8	None			

SYRACUSE CITY SCHOOL DISTRICT FRANKLIN ELEMENTARY SCHOOL

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	07/21/23 RESULTS (ppb)	07/21/23 ACTIONS	LAB RE-SAMPLE I.D. No.	04/03/24 RE-SAMPLE RESULTS (ppb)	04/03/24 RE-SAMPLE ACTIONS
Rm. 131 - Kitchen	Sink	Secured - SCSD Staff Only	039	FN-S114	2.2	None			
Rm. 131 - Kitchen	Sink	Secured - SCSD Staff Only	041	FN-S115	1	None			
Rm. 146C - Cafeteria Passage	Fountain	Public Access	043	FN-F202	<1.0	None			
Rm. 125 - Classroom	Sink	Public Access	035	FN-S202	3	None			
Rm. 202 - Clinic Room	Sink	Public Access	017	FN-S211	2.4	None			
Rm. 202 - Clinic Room	Sink	Public Access	018	FN-S212	2.4	None			
Rm. 202 - Clinic/Examination Room	Sink	Public Access	020	FN-S213	2.2	None			
Rm. 202 - Clinic Room	Sink	Public Access	021	FN-S215	1.5	None			
Rm. 204 - Clinic Room	Sink	Public Access	016	FN-S210	1.7	None			
Rm. 124 - Classroom	Sink	Public Access	064	FN-S201	2.3	None			
Rm. 210 - Classroom	Sink	Public Access	032	FN-FA	<1.0	None			
Rm. 212D - Hallway/Vestibule	Sink	Public Access	023	FN-S122	<1.0	None			
Rm. 212D - Hallway/Vestibule	Sink	Public Access	024	FN-S123	3.8	None			
Rm. 212D - Hallway/Vestibule	Sink	Public Access	026	FN-S124	<1.0	None			
Rm. 212D - Hallway/Vestibule	Fountain	Public Access	025	FN-F108	<1.0	None			
Rm. 215 - Computer Room	Sink	Public Access	027	FN-S126	2.0	None			
Rm. 215 - Computer Room	Fountain	Public Access	028	FN-F110	1.5	None			
Rm. 216 - Computer Room	Sink	Public Access	029	FN-S125	1.6	None			
Rm. 216 - Computer Room	Fountain	Public Access	030	FN-F109	1.1	None			
Rm. 220A - Classroom Bathroom	Sink	Public Access		FN-S121		See Note 7.	001	<1.0	None
Rm. 228B - Office Kitchenette	Sink	Secured - SCSD Staff Only	031	FN-S118	<1.0	None			
Rm. 234 - Hallway/Corridor	Fountain	Public Access	033	FN-F111	<1.0	None			
Rm. 307 - Hallway/Vestibule	Sink	Public Access	008	FN-S139	1.2	None			
Rm. 307 - Hallway/Vestibule	Sink	Public Access	006	FN-S140	<1.0	None			
Rm. 307 - Hallway/Vestibule	Sink	Public Access	005	FN-S141	<1.0	None			
Rm. 307 - Hallway/Vestibule	Fountain	Public Access	007	FN-F114	<1.0	None			
Rm. 309 - Classroom	Fountain	Public Access	009	FN-F113	1.0	None			
Rm. 310 - Classroom	Sink	Public Access	010	FN-S137	2.8	None			
Rm. 310 - Classroom	Fountain	Public Access	011	FN-F112	1.3	None			
Rm. 319 - Hallway/Vestibule	Sink	Public Access	001	FN-S219	2.4	None			

SYRACUSE CITY SCHOOL DISTRICT FRANKLIN ELEMENTARY SCHOOL

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	07/21/23 RESULTS (ppb)	07/21 /23 ACTIONS	LAB RE-SAMPLE I.D. No.	04/03/24 RE-SAMPLE RESULTS (ppb)	04/03/24 RE-SAMPLE ACTIONS
Rm. 319 - Hallway/Vestibule	Sink	Public Access	002	FN-S220	<1.0	None			
Rm. 319 - Hallway/Vestibule	Sink	Public Access	004	FN-S221	3.0	None			
Rm. 319 - Hallway/Vestibule	Fountain	Public Access	003	FN-F208	1.3	None			
Rm. 131 - Kitchen	iCombi Pro Oven Sprayer	Secured - SCSD Staff Only	042	FN-S4000	3.3	None			

Notes [July 21, 2023 Event]:

- 1. Water samples collected by: TDK Engineering Associates, P.C. TDK Project No. 2016068-007.
- 2. Water samples analyzed by: Pace Analytical Services, LLC Pace Project No. 70264172.
- 3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
- 4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) Subpart 67-4: Lead Testing in School Drinking Water.
- 5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
- 6. Fixture removed and replaced by SCSD.
- 7. Fixture repaired by SCSD.
- 8. Fixture signed by SCSD. No further action required.

Notes [April 3, 2024 Event]:

- 1. Water samples collected by: TDK Engineering Associates, P.C. TDK Project No. 2016068-007.
- 2. Water samples analyzed by: Pace Analytical Services, LLC Pace Project No. 70292835.
- 3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
- 4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) Subpart 67-4: Lead Testing in School Drinking Water.
- 5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.

