

SYRACUSE CITY SCHOOL DISTRICT
VAN DUYN ELEMENTARY SCHOOL

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	09/26/23 RESULTS (ppb)	09/26/23 ORIGINAL ACTIONS	LAB RE-SAMPLE I.D. No.	04/11/24 RE-SAMPLE RESULTS (ppb)	04/11/24 RE-SAMPLE ACTIONS	LAB RE-SAMPLE I.D. No.	10/03/25 RE-SAMPLE RESULTS (ppb)	10/03/25 RE-SAMPLE ACTIONS
Rm. 001 - Cafeteria	Fountain	Public Access	048	VN-F100	<1.0	None	---	---	See Note 7.	001	<0.1	None
Rm. 001 - Cafeteria	Bottel Fill	Public Access	048	VN-F100A	---	---	---	---	See Note 7.	002	<0.1	None
Rm. 001 - Cafeteria	Fountain	Public Access	049	VN-F101	<1.0	None	---	---	---	---	---	---
Rm. 0B8 - Kitchen	Sink	Secured - SCSD Staff Only	050	VN-S101	<1.0	None	---	---	---	---	---	---
Rm. 0B8 - Kitchen	Sink	Secured - SCSD Staff Only	051	VN-S102	<1.0	None	---	---	---	---	---	---
Rm. 0B8 - Kitchen	Sink	Secured - SCSD Staff Only	052	VN-S103	<1.0	None	---	---	---	---	---	---
Rm. 0B8 - Kitchen	Sink	Secured - SCSD Staff Only	053	VN-S104	1.6	None	---	---	---	---	---	---
Rm. 031 - Hallway/Corridor	Fountain	Public Access	042	VN-F102	<1.0	None	---	---	---	---	---	---
Rm. 031 - Hallway/Corridor	Fountain	Public Access	043	VN-F102A	<1.0	None	---	---	---	---	---	---
Rm. 0B1A - Hallway/Vestibule	Sink	Public Access	044	VN-S105	4.8	None	---	---	---	---	---	---
Rm. 0B1A - Hallway/Vestibule	Sink	Public Access	045	VN-S106	<1.0	None	---	---	---	---	---	---
Rm. 0B1A - Hallway/Vestibule	Sink	Public Access	046	VN-S107	<1.0	None	---	---	---	---	---	---
Rm. 0B1A - Hallway/Vestibule	Sink	Public Access	047	VN-S108	2.4	None	---	---	---	---	---	---
Rm. 005 - Classroom	Sink	Public Access	041	VN-S109	<1.0	None	---	---	---	---	---	---
Rm. 010A - Office	Sink	Secured - SCSD Staff Only	040	VN-S110	24.9	See Note 7.	002	2.5	None	---	---	---
Rm. 134 - Classroom	Sink	Public Access	018	VN-S111	1.9	None	---	---	---	---	---	---
Rm. 100M - Hallway/Corridor	Fountain	Public Access	016	VN-F103	<1.0	None	---	---	See Note 7.	003	<0.1	None
Rm. 100M - Hallway/Corridor	Bottel Fill	Public Access	016	VN-F103A	---	---	---	---	See Note 7.	004	<0.1	None
Rm. 132 - Classroom	Sink	Public Access	015	VN-S112	<1.0	None	---	---	---	---	---	---
Rm. 135 - Classroom	Sink	Public Access	019	VN-S113	<1.0	None	---	---	---	---	---	---
Rm. 133 - Classroom	Sink	Public Access	017	VN-S114	<1.0	None	---	---	---	---	---	---
Rm. 128 - Classroom	Sink	Public Access	021	VN-S115A	2.6	None	---	---	---	---	---	---
Rm. 129 - Classroom	Sink	Public Access	020	VN-S115B	<1.0	None	---	---	---	---	---	---
Rm. 123 - Classroom	Sink	Public Access	014	VN-S117	1.7	None	---	---	---	---	---	---
Rm. 123 - Classroom	Fountain	Public Access	013	VN-F104	<1.0	None	---	---	---	---	---	---
Rm. 120 - Classroom	Sink	Public Access	011	VN-S118	1.5	None	---	---	---	---	---	---
Rm. 120A - Classroom Bathroom	Sink	Public Access	012	VN-S119	6.4	See Note 7.	006	<1.0	None	---	---	---
Rm. 109 - Nurse's Room	Sink	Public Access	024	VN-S120	7.3	See Note 6.	003	2.8	None	---	---	---

SYRACUSE CITY SCHOOL DISTRICT
VAN DUYN ELEMENTARY SCHOOL

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	09/26/23 RESULTS (ppb)	09/26/23 ORIGINAL ACTIONS	LAB RE-SAMPLE I.D. No.	04/11/24 RE-SAMPLE RESULTS (ppb)	04/11/24 RE-SAMPLE ACTIONS	LAB RE-SAMPLE I.D. No.	10/03/25 RE-SAMPLE RESULTS (ppb)	10/03/25 RE-SAMPLE ACTIONS
Rm. 117 - Classroom	Sink	Public Access	010	VN-S122	<1.0	None	---	---	---	---	---	---
Rm. 109A - Exam Room	Sink	Public Access	028	VN-S123	12.5	See Note 7.	004	<1.0	None	---	---	---
Rm. 119D - Work Room	Sink	Secured - SCSD Staff Only	023	VN-S126	20.3	See Note 6.	005	24.6	See Note 6.	---	---	---
Rm. 115E - Lounge Kitchenette	Sink	Secured - SCSD Staff Only	022	VN-S127	<1.0	None	---	---	---	---	---	---
Rm. 0A8 - Hallway/Corridor	Fountain	Public Access	--	VN-F200	---	See Note 6.	001	2.6	See Note 7.	005	<0.1	None
Rm. 0A8 - Hallway/Corridor	Fountain	Public Access	--	VN-F200A	---	---	---	---	See Note 7.	006	<0.1	None
Rm. 023 - Classroom	Sink	Public Access	033	VN-S201	<1.0	None	---	---	---	---	---	---
Rm. 023 - Classroom	Sink	Public Access	034	VN-S202	2.1	None	---	---	---	---	---	---
Rm. 023A - Classroom	Sink	Public Access	035	VN-S203	1.4	None	---	---	---	---	---	---
Rm. 023A - Classroom	Sink	Public Access	036	VN-S204	<1.0	None	---	---	---	---	---	---
Rm. 021 - Kitchen Room	Sink	Secured - SCSD Staff Only	037	VN-S205	<1.0	None	---	---	---	---	---	---
Rm. 020A - Classroom	Sink	Public Access	038	VN-S206	2.4	None	---	---	---	---	---	---
Rm. 020A - Classroom	Sink	Public Access	039	VN-S207	<1.0	None	---	---	---	---	---	---
Rm. 024 - Classroom	Sink	Public Access	029	VN-S208	<1.0	None	---	---	---	---	---	---
Rm. 024 - Classroom	Sink	Public Access	030	VN-S209	1.2	None	---	---	---	---	---	---
Rm. 022 - Classroom	Sink	Public Access	031	VN-S210	<1.0	None	---	---	---	---	---	---
Rm. 022 - Classroom	Sink	Public Access	032	VN-S211	<1.0	None	---	---	---	---	---	---
Rm. 100P - Hallway/Corridor	Fountain	Public Access	025	VN-F201	<1.0	None	---	---	See Note 7.	007	<0.1	None
Rm. 100P - Hallway/Corridor	Bottel Fill	Public Access	025	VN-F201A	---	---	---	---	See Note 7.	008	<0.1	None
Rm. 103 - Gym	Fountain	Public Access	027	VN-F202	<1.0	None	---	---	---	---	---	---
Rm. 103 - Gym	Fountain	Public Access	026	VN-F203	<1.0	None	---	---	---	---	---	---
Rm. 108 - Classroom	Sink	Public Access	008	VN-S219	<1.0	None	---	---	---	---	---	---
Rm. 110 - Classroom	Sink	Public Access	007	VN-S220	<1.0	None	---	---	---	---	---	---
Rm. 111 - Classroom	Sink	Public Access	006	VN-S221	<1.0	None	---	---	---	---	---	---
Rm. 113 - Office	Sink	Secured - SCSD Staff Only	009	VN-S222	1	None	---	---	---	---	---	---
Rm. 230 - Hallway/Corridor	Fountain	Public Access	001	VN-F301	<1.0	None	---	---	See Note 7.	009	<0.1	None
Rm. 230 - Hallway/Corridor	Fountain	Public Access	001	VN-F301A	---	---	---	---	See Note 7.	010	<0.1	None

SYRACUSE CITY SCHOOL DISTRICT
VAN DUYN ELEMENTARY SCHOOL

ROOM No. & LOCATION	FIXTURE (Sink/Fountain)	ACCESSIBILITY	LAB SAMPLE I.D. No.	TDK SAMPLE I.D. No.	09/26/23 RESULTS (ppb)	09/26/23 ORIGINAL ACTIONS	LAB RE-SAMPLE I.D. No.	04/11/24 RE-SAMPLE RESULTS (ppb)	04/11/24 RE-SAMPLE ACTIONS	LAB RE-SAMPLE I.D. No.	10/03/25 RE-SAMPLE RESULTS (ppb)	10/03/25 RE-SAMPLE ACTIONS
Rm. 207 - Teacher Resource	Sink	Secured - SCSD Staff Only	002	VN-S307	1.6	None	---	---	---	---	---	---
Rm. 231 - Hallway/Corridor	Fountain	Public Access	001	VN-F302	---	---	---	---	See Note 7.	011	<0.1	None
Rm. 231 - Hallway/Corridor	Bottel Fill	Public Access	001	VN-F302A	---	---	---	---	See Note 7.	012	<0.1	None.
Rm. 227A - Laboratory	Sink	Public Access	005	VN-S315	1.4	None	---	---	---	---	---	---
Rm. 227A - Laboratory	Sink	Public Access	004	VN-S316	1.2	None	---	---	---	---	---	---
Rm. 0B8 - Kitchen	Convotherm Oven Sprayer	Secured - SCSD Staff Only	054	VN-C1000	<1.0	None	---	---	---	---	---	---
Rm. 227F - Work Room	Sink	Public Access	003	VN-S3000	61.1	See Note 7.	008	2.5	None	---	---	---

Notes: [September 26, 2023 Event]

1. Water samples collected by: TDK Engineering Associates, P.C. - TDK Project No. 2016068-014.
2. Water samples analyzed by: Pace Analytical Services, LLC - Pace Project No. 70272048.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture repaired by SCSD.
7. Fixture removed and replaced by SCSD.

Notes: [April 11, 2024 Event]

1. Water samples collected by: TDK Engineering Associates, P.C. - TDK Project No. 2016068-014.
2. Water samples analyzed by: Pace Analytical Services, LLC - Pace Project No. 70293944.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.
6. Fixture signed and to be removed by SCSD. No further action required.
7. Fountain removed and replaced with combined fountain/bottle fill station.

Notes: [October 3, 2025 Event]

1. Water samples collected by: TDK Engineering Associates, P.C. - TDK Project No. 2016068-014.
2. Water samples analyzed by: Pace Analytical Services, LLC - Pace Project No. 70383746.
3. New York State Department of Health Standard for Lead in Drinking Water is 5 parts per billion (ppb).
4. The water sampling and analysis program was conducted in substantial conformance with Title 10 (Health) of Official Compilation Codes, Rules and Regulations of the State of New York (10NYCRR) - Subpart 67-4: Lead Testing in School Drinking Water.
5. Water Samples Analyzed for Metals (Lead) in Accordance with EPA 200.8.